



INSPECCIÀ EVALUACIÀ — ADVANCED — SKID STEER AUGUST 3, 2020

2017 Bobcat E35
Inventario: 258393
Número de serie: AR1K13512
Garantía desconocida

LOCALIDAD ALMACENAMIENTO
Pattison Agriculture Limited / 731798
Yorkton, SK, S3N3N5
Contacto:

FOTOS (0 Total)

RESUMEN

Estado general:
Comentarios
generales:
Horas:

								Coste estimado		
	EXCELENTE	BIEN	MEDIANO	RAZONABLE	MALE	N/A	Observaciones	Repuestos	Mano de obra	Total
								0	0	0
unit								0	0	0
attachment								0	0	0
features:								0	0	0
inspection/conditions:								0	0	0

Stock Number: 258393

Model: E35

Serial Number: AR1K13512

							Coste estimado		
	N U E V O	B I E N	U S A B L E	R E P A R A R	C A M B I A R	N D	Observaciones	Repuestos	Mano de obra Total
Company							TDX CONTRACTING INC.		
Phone #									
Customer # 1									

UNIT

							Coste estimado		
	N U E V O	B I E N	U S A B L E	R E P A R A R	C A M B I A R	N D	Observaciones	Repuestos	Mano de obra Total
Make:							BOCBAT		
Model							E35		
Serial #							AR1K13512		
Year:							2017		
Hours:							3082		
Unit Primary Application									

ATTACHMENT

							Coste estimado		
	N U E V O	B I E N	U S A B L E	R E P A R A R	C A M B I A R	N D	Observaciones	Repuestos	Mano de obra Total
Make:							BOCBAT		
Model							36" GRADING		
Serial #									
Year:									
Picture Process									

FEATURES:

							Coste estimado		
	N U E V O	B I E N	U S A B L E	R E P A R A R	C A M B I A R	N D	Observaciones	Repuestos	Mano de obra Total
1- Engine: Size									
HP							33		
2- Forks:							✓ No		
3- Bucket:							✓ Yes		
4- Size:									
5- Hydraulic Options:							✓ Auxiliary Hydraulics HYD X-CHANGE		
6- Options:							✓ Back Up Alarm		
7- Warranty: Terms							NONE		

Stock Number: 258393

Model: E35

Serial Number: AR1K13512

INSPECTION/CONDITIONS:

								Coste estimado		
	N U E V O	B I E N	U S A B L E	R E P A R A B L E	C A M B I A R E	N D	Observaciones	Repuestos	Mano de obra	Total
Pre Start Contamination Checks:										
Leaks-										
A. Interior-							CLEAN			
1. Cab/Seat/Glass Condition:							✓ Good			
B. Tires							GOOD			
2. Front Tires: Size										
Condition										
% Tread Remaining										
3. Rear Tires: Size										
Condition										
% Tread Remaining										
C. Engine, Cooling and Fuel Systems:										
Engine Running Test for Power, Leaks, Unusual Noises or Smoke:							FEW LEAKS ON SOME HOSES			
D. Powertrain:										
5. Transmission & Controls Operations:							✓ Good			
6. Axles, Housings, Seats & Bearings:							✓ Good			
E. Electrical Systems:										
7. Battery, Cables & Wiring Harness:							✓ Good			
8. Starter Switch, Motor & Neutral safety System							✓ Good			
9. Lights, Warning Lights & Turn Signals							✓ Good			
F. Operators Station:										
10. Heater & A/C System and Operation							✓ Good			
11. Door Latch, and Hinges Condition & Operation										
G. Miscellaneous:										
12. Chassis, Frame, Weights & Hardware							✓ Good			
13. Sheet Metal & Paint Condition & Appearance							✓ Good			
H. Frame & Transport Components:										
14. Main Frame							✓ Good			
15. Wheels & Tires							✓ Good			
I. Safety Equipment:										
16. Oil, Fuel & Coolant Leaks							SOME LEAKS			
17. All Safety Shields, Covers & Shrouds							✓ Good			
18. SMV, Safety Decals, & Warning Devices							✓ Good			
19. Steps, Handrails, Fenders, Guards							✓ Good			
J. Exterior							NICE			
20. Mirrors, Exhaust, Glass, Condition of Exterior:							✓ Good			
k. Function Test **IF POSSIBLE AND WITH PERMISSION ONLY. Run and Test all Functions**							✓ Good			
L. Summary:							UNIT HAS DONE A LOT OF WORK BUT HAS BEEN WELL MAINTAINED AND LOOKS NICE, ALWAYS SERVICED HERE, OIL WAS CHANGED AT 3000HRS			