

Stock Number: C149941

Model: 410R Serial Number: 1N0410RXCN0222673



### INSPECCIÒN EVALUACIÒN — ADVANCED — SPRAYER INSPECTION FORM

2022 John Deere 410R  
Inventario: C149941  
Número de serie: 1N0410RXCN0222673  
Garantía desconocida

LOCALIDAD ALMACENAMIENTO  
**21st Century Equipment, LLC / 067245**  
Greeley, CO, 80631  
Contacto:

### FOTOS (0 Total)

### RESUMEN

Estado general:  
Comentarios  
generales:  
Horas:

	EXCELENTE	BIEN	MEDIANO	RAZONABLE	MAL	N/A	Observaciones	Coste estimado		
								Repuestos	Mano de obra	Total
Machine Entry Form								0	0	0
ENGINE & Transmission								0	0	0
Features								0	0	0
Solution System Control								0	0	0
Cab								0	0	0
AMS Equipment (Trading with unit)								0	0	0
ADDITIONAL OPTIONS								0	0	0
Inspection/Conditions								0	0	0
Tires								0	0	0
Exterior Condition (Explain repairs needed)								0	0	0
Equipos de Seguridad								0	0	0
Service								0	0	0

Stock Number: C149941

Model: 410R Serial Number: 1N0410RXCN0222673

**MACHINE ENTRY FORM**

	NUEVO	BIEN	USABLE	REPARAR	CAMBIAR	ND	Observaciones	Coste estimado		
								Repuestos	Mano de obra	Total
Manufacturer:							John Deere			
Model:							410R			
Engine Hours:							1600 est hrs 9.1.2025			
Spray Hours:										
Serial Number:							222673			
Customer/Farm Name:							Nutrien Greeley			
What are they trading on?							410R			
Idea what they want for it?										
Estimated Recon \$?							\$6645 from winter 25 inspection Figure \$8000 total			
Estimated Trade #?							Does have a lincoln auto lube system on it as well			
Do you need Jockey/Wholesale Bid? <input type="radio"/> Si <input checked="" type="radio"/> No										

**ENGINE & TRANSMISSION**

	NUEVO	BIEN	USABLE	REPARAR	CAMBIAR	ND	Observaciones	Coste estimado		
								Repuestos	Mano de obra	Total
Engine HP:										
Make:							Deere			
Size:							9.0			
Transmission:							<input checked="" type="checkbox"/> 4WD			

**FEATURES**

	NUEVO	BIEN	USABLE	REPARAR	CAMBIAR	ND	Observaciones	Coste estimado		
								Repuestos	Mano de obra	Total
Suspension:							<input checked="" type="checkbox"/> Auto			
Tank Size (Gal):							1000			
Tank Material:							<input checked="" type="checkbox"/> Stainless			
Boom Size:							<input checked="" type="checkbox"/> 100'			
Boom Material:							<input checked="" type="checkbox"/> Steel			
Plumbing Material:							<input checked="" type="checkbox"/> Stainless			
Nozzle:							<input checked="" type="checkbox"/> EA 6 way			
Nozzle Spacing:							<input checked="" type="checkbox"/> 15"			
Nozzle Control:							<input checked="" type="checkbox"/> Exact Apply			
Height Control:							<input checked="" type="checkbox"/> Boomtrac			
Front/Side Fill:							<input checked="" type="checkbox"/> Front Fill			

**SOLUTION SYSTEM CONTROL**

	NUEVO	BIEN	USABLE	REPARAR	CAMBIAR	ND	Observaciones	Coste estimado		
								Repuestos	Mano de obra	Total
Auto/ Manual?							<input checked="" type="checkbox"/> Auto			
Chem Educator? <input checked="" type="checkbox"/> Si <input type="checkbox"/> No										
On Board Air? <input checked="" type="checkbox"/> Si <input type="checkbox"/> No										

Stock Number: C149941

Model: 4100 Serial Number: 1N0410RXCN0222673

**CAB**

	NUEVO	BIEN	USABLE	REPARAR	CAMBIAR	ND	Observaciones	Coste estimado		
								Repuestos	Mano de obra	Total
Cab Type:							✓ Premium			
Smoked in? <input type="radio"/> Si <input checked="" type="radio"/> No										
A/C working? <input checked="" type="radio"/> Si <input type="radio"/> No										
Missing or broken items? <input type="radio"/> Si <input checked="" type="radio"/> No										
Seats:							✓ Leather			
Lighting:							✓ LED			
Radio? <input checked="" type="radio"/> Si <input type="radio"/> No										
Traction Control? <input checked="" type="radio"/> Si <input type="radio"/> No										
Boom Air Purge? <input checked="" type="radio"/> Si <input type="radio"/> No										
Spray Test? <input checked="" type="radio"/> Si <input type="radio"/> No										

**AMS EQUIPMENT (TRADING WITH UNIT)**

	NUEVO	BIEN	USABLE	REPARAR	CAMBIAR	ND	Observaciones	Coste estimado		
								Repuestos	Mano de obra	Total
Display #1 Make:							4600 Command Center			
Model:							4.0 prem activation auto trac section control			
Serial #:										
Display #2 Make:										
Model:										
Serial #:										
Receiver Make:							john deere			
Model:							sf6000			
Serial #:										
							✓ SF1 this receiver was not on the lease- owned outright, but I would like to trade with the sprayer			
Activations:							✓ Auto Trac Prem 4.0 act			

**ADDITIONAL OPTIONS**

	NUEVO	BIEN	USABLE	REPARAR	CAMBIAR	ND	Observaciones	Coste estimado		
								Repuestos	Mano de obra	Total
Are Nozzles staying with machine? <input checked="" type="radio"/> Si <input type="radio"/> No										
Are Tips staying with machine? <input type="radio"/> Si <input checked="" type="radio"/> No										
Fence Row Nozzles:							<input checked="" type="checkbox"/> LH			
Flow Meter:							<input checked="" type="checkbox"/> Dual			
Pump:							<input checked="" type="checkbox"/> High Flow			
Additions (mark all that apply):							<input checked="" type="checkbox"/> Hyd. Tread Adjust			

**INSPECTION/CONDITIONS**

	NUEVO	BIEN	USABLE	REPARAR	CAMBIAR	ND	Observaciones	Coste estimado		
								Repuestos	Mano de obra	Total
Pre start fluid contamination (check the following fluids)										
Any leaks? Please comment <input type="radio"/> Si <input checked="" type="radio"/> No										
Emissions are original factory? (NOT DELETED)							<input checked="" type="checkbox"/> Yes			

**TIRES**

	NUEVO	BIEN	USABLE	REPARAR	CAMBIAR	ND	Observaciones	Coste estimado		
								Repuestos	Mano de obra	Total
What tires will be traded with machine? Set #1							<input checked="" type="checkbox"/> Standard			
[tire_cond:sprayer]										
Tire tread remaining %							<input checked="" type="checkbox"/> Good 75%+			
Cuts or damage? <input type="radio"/> Si <input checked="" type="radio"/> No										
Any low, leaking or flat? <input type="radio"/> Si <input checked="" type="radio"/> No										
Second set of tires? (Floaters) <input type="radio"/> Si <input checked="" type="radio"/> No										
[tire_cond:sprayer]										
Tire tread remaining %										
Cuts or damage? <input type="radio"/> Si <input type="radio"/> No										

Stock Number: C149941

Model: 410SR Serial Number: 1N0410RXCN0222673

**EXTERIOR CONDITION (EXPLAIN REPAIRS NEEDED)**

	NUEVO	BIEN	USABLE	REPARAR	CAMBIAR	ND	Observaciones	Coste estimado		
								Repuestos	Mano de obra	Total
Ladder & Platform							✓ Good			
Booms							✓ Good			
Front Steering Cyl, Tread Adjust Cyl, Drive Motor/Seal, Fenders, Suspension Airbag:							✓ Good			
Rinse Tank, Side Fill, Hoses, Hyd Lines:							✓ Good			
Solution Pump./Hyd Motor, Belly hoses:							✓ Good			
Filters/Strainers, Boom lift cylinders:							✓ Good			
Belly plates, Oil Filters, Product hoses:							✓ Good			

**EQUIPOS DE SEGURIDAD**

	NUEVO	BIEN	USABLE	REPARAR	CAMBIAR	ND	Observaciones	Coste estimado		
								Repuestos	Mano de obra	Total
All safety shields, covers and shrouds							✓ OK			
SMV, safety decals and warning devices							✓ OK			

**SERVICE**

	NUEVO	BIEN	USABLE	REPARAR	CAMBIAR	ND	Observaciones	Coste estimado		
								Repuestos	Mano de obra	Total
21st Century Equipment serviced annually? <input checked="" type="checkbox"/> Si <input type="checkbox"/> No							latest 25 Uptime Inspection on this unit			
21st Century Equipment pervious work orders?							Inspections and repairs. They do their own fluid/ filter service			
Has Sprayer been winterized? <input checked="" type="checkbox"/> Si <input type="checkbox"/> No										