



INSPECCIÀ EVALUACIÀ — ADVANCED — AIR SEEDING JANUARY 2023

2012 Vaderstad 72-12
Inventario: 257425
Número de serie: 121146
Garantía desconocida

LOCALIDAD ALMACENAMIENTO
Pattison Agriculture Limited / 731850
Preeceville, SK, S0A3B0
Contacto:

FOTOS (0 Total)

RESUMEN

Estado general:
Comentarios
generales:
Horas:

							Coste estimado			
	EXCELENTE	BIEN	MEDIANO	RAZONABLE	MALE	N/A	Observaciones	Repuestos	Mano de obra	Total
								0	0	0
MAIN FEATURES TO BE ADVERTISED - FILL IN FEATURES SECTION OF MFPRO								0	0	0
INSPECTION/CONDITIONS-TOOL								0	0	0
INSPECTION/CONDITIONS-CART								0	0	0

Stock Number: 257425

Model: 72-12

Serial Number: 121146

								Coste estimado		
	NUEVO	BIEN	USABLE	REPARAR	CAMBIA	ND	Observaciones	Repuestos	Mano de obra	Total
Customer:							MICHAEL FLOWERS			
Tool: Year: Make: Model:							2012 Vaderstad 72-12			
Serial Number:							121146			
Cart: Year: Make: Model:							2009 Bourgault L6450			
Serial Number:							39861AS-08			
Acres:							CUSTOMER SAYS UNKNOWN			
Link to Picture Process:										

MAIN FEATURES TO BE ADVERTISED - FILL IN FEATURES SECTION OF MFPRO

								Coste estimado		
	N U E V O	B I E N	U S A B L E	R E P A R A R	C A M B I A R	N D	Observaciones	Repuestos	Mano de obra	Total
Tool							72' Air Drill			
1- Make: Model: Spacing							✓ Double Shoot Vaderstad 72-12 w/ 12" Spacing			
2- MRB/ MRS Type										
3- Fertilizer Type							✓ NH3			
4- # of Runs							16 Run 8 Fert/8 Seed			
5- Openers							✓ Independent Opener			
Tips Size/ Style							Inline 1/2" Cabide Tip			
6- Frame										
7- Blockage Brand							✓ AG Tron			
8- Runs							✓ Fert 2 Sensors Per Manifold			
9- Packers							✓ Semi-Pneumatic			
Cart							✓ TBT			
10- BU size							450 Bushel Tank			
11- Tank Split							145/15/60/230 Tank Split			
12- Scale										
13- Shoot							✓ Double			
14- Meters							✓ Ground Driven			
# of Meters/ Color of Meter Rollers							3 Meters			
15- # of Primary Runs							2 Primary Runs			
16- Unload Systems Size							10" Unloading Auger			
17- Auger							✓ Auger			
18- Fans							✓ Dual			
19- Misc							✓ Bag Lift			
20- # Cameras/ Location							3 Camera's 2nd, 3rd and Rear View			
21- Front Tires: Brand and Size										
Rear Tires: Brand and Size							Goodyear 650/75R34 Duals			
22- Monitor #1 Brand/ Model							591 Bourgault Monitor (AS PER CUSTOMER)			
Serial Number										
Monitor #2 Brand/ Model										
Serial Number:										

INSPECTION/CONDITIONS-TOOL

							Coste estimado		
	N U E V O	B I E N	U S A B L E	R E P A R A R	C A M B I A R	N D	Observaciones	Repuestos	Mano de obra Total
							✓ Operations Manual No		
1- Hitch & Frame							✓ Cracks some cracking on frame, needs to be welded, recommend laying unit down and checking all welds, some re welding has been done as shown in pictures, Noticed a bolt broke on brace on left side as well shown in picture		
Wing Cylinders							✓ Good appear to be good		
2- Openers							✓ Good		
Acres on Openers							unknown customer does not know acres on drill		
Shank Cylinders							✓ N/R majority of them are leaking to some extent, sot saying they don't work but this expense will need to be done sooner than later		
3- Drop Tubes Type									
4- MRB/ MRS									
5- Disc/Tips							✓ Good		
6- Width (Include Tape Measure-Bourgault 4 1/2; from hub replace)									
7- Packers							✓ Good		
Width (include Tape Measurement)									
9- Transport Front Tires Condition and % Remaining							front implement style look to be in good condition with minimal cracking rear left has been changed out, right rear appears to be good but must have a leak as it was low on pressure		
Wing Tires Condition							✓ Duals wing Gauge wheels are cracking between tread as shown in one picture		
10- Towers/ Blockage Monitors							✓ Good appear to be good		
11- Primary & Secondary Hoses							✓ N/R some will need to be replaced, but for 1/2 of the primary and 1/4 of the secondary		
12- NH3 or Liquid Kit & Controls							✓ Good some hoses not in openers? customer says it has a JD rate controller		
13- Shank Bushing & Openers-Sample Several different Locations							✓ N/R believe some to be good, some will need tightening, picture of the worst shown, noticed one set of openers is closer together than the next as shown in a picture, should be gone through		
14- Front Casters (more then a dime on a Bourgault Nylotron washer indicated need for adjustment/wear)							✓ N/R should be adjusted		
Overall Summary of Tool							unit needs some work as listed above with the leaking cylinders on the openers being the biggest expense, would recommend budgeting higher for repairs as listed above		

Stock Number: 257425

Model: 72-12

Serial Number: 121146

INSPECTION/CONDITIONS-CART

							Coste estimado			
	N U E V O	B I E N	U S A B L E	R E P A R A R	C A M B I A R	N D	Observaciones	Repuestos	Mano de obra	Total
							✓ Operations Manual No			
1- Meters: Feed Rollers/Augers (Confirm w/ TM if Going w/ Unit)							✓ Poly			
Condition							✓ Good take it that they are good as customer was using			
Meter Drives							✓ Good			
Sectional Control Cylinders										
Manifolds							✓ Good manifolds look okay but do see some duct tape on piping between cart and drill see picture			
2- Load/Unload System							Leak on some hyd hoses and auger corroded pretty good, maybe budget for some re work?, outside of auger looks pretty good except at the hopper split as it is ductaped and corroded in this area pretty good			
Condition							✓ N/R			
3- Front Tires- Condition and % Remaining										
Measured vs New Tread Height										
Rear Tires/ Tracks - Condition and % Remaining							average condition with the cracking versus year, not to concerned about the tread face cracking more concerned about the sidewall cracking on 3 of the tires, unsure how long they will last but will effect resale value			
Measured vs New Tread Height										
4- Cart/ Frame/ Tank Lids							✓ Rust good but has some surface rusting			
5- Tank Compartments/ Tank Seals/ Gas Cyl.							✓ Good appear to be good			
Overall Summary of Cart							average condition for a tank that sits outside, parts of the loading auger and tires will hamper the resale value a little. not sure if some or any of the cameras work? Safety chain latch missing right rear warning light bracket bent			