

Stock Number: 698744

Model: 1596

Serial Number: B36970122

INSPECCIÒN EVALUACIÒN — ADVANCED — BRANDT GRAIN CARTS

2019 Brent 1596
Inventario: 698744
Número de serie: B36970122
Garantía desconocida

LOCALIDAD ALMACENAMIENTO
Valley Plains Equipment / 084766
PO Box 338
MILNOR, ND, 58060
Contacto:

FOTOS (0 Total)

RESUMEN

Estado general:
Comentarios
generales:
Horas:

	EXCELENTE	BIEN	MEDIANO	RAZONABLE	MAL	N/A	Observaciones	Coste estimado		
								Repuestos	Mano de obra	Total
Brandt Grain Carts								0	0	0
Availability Date								0	0	0
Type								0	0	0
Bushel Capacity								0	0	0
Discharge Auger Size								0	0	0
Tire Size/Track width								0	0	0
Accessories								0	0	0
Controls								0	0	0
PHOTOS- minimum required pictures for evaluation								0	0	0
BMLSS- BROKEN-MISSING-LEAKING-SAFETY-SERVICE-								0	0	0
Pricing								0	0	0

Stock Number: 698744

Model: 1596

Serial Number: B36970122

BRANDT GRAIN CARTS

										Coste estimado		
NUEVO	BIEN	USABLE	REPARAR	CAMBIA R	N D	Observaciones	Repuestos	Mano de obra	Total			

AVAILABILITY DATE

										Coste estimado		
NUEVO	BIEN	USABLE	REPARAR	CAMBIA R	N D	Observaciones	Repuestos	Mano de obra	Total			
What is your anticipated availability date for this item? What is the MM/DD/YY this will be ready to deliver to the next buyer?						✓ What is your anticipated availability date for this item? When will it be on the lot ready to deliver to the next buyer? 10/7/25						

TYPE

										Coste estimado		
NUEVO	BIEN	USABLE	REPARAR	CAMBIA R	N D	Observaciones	Repuestos	Mano de obra	Total			
What Type						✓ Grain Cart						
Drive						✓ 1000 PTO						

BUSHEL CAPACITY

										Coste estimado		
NUEVO	BIEN	USABLE	REPARAR	CAMBIA R	N D	Observaciones	Repuestos	Mano de obra	Total			
Capacity in Bushels						1500						

DISCHARGE AUGER SIZE

										Coste estimado		
NUEVO	BIEN	USABLE	REPARAR	CAMBIA R	N D	Observaciones	Repuestos	Mano de obra	Total			
Discharge Auger Diameter						✓ 22"						

TIRE SIZE/TRACK WIDTH

										Coste estimado		
NUEVO	BIEN	USABLE	REPARAR	CAMBIA R	N D	Observaciones	Repuestos	Mano de obra	Total			
Type						✓ Walking Tandem Tires 900/60R32						
Tire-Track Size (put in notes)												

ACCESSORIES

										Coste estimado		
NUEVO	BIEN	USABLE	REPARAR	CAMBIA R	N D	Observaciones	Repuestos	Mano de obra	Total			
Options						✓ Roll Tarp uharvest						

CONTROLS

	NUEVO	BIEN	USABLE	REPARAR	CAMBIAR	ND	Observaciones	Coste estimado		
								Repuestos	Mano de obra	Total
Seed Tender remote control										

PHOTOS- MINIMUM REQUIRED PICTURES FOR EVALUATION

	NUEVO	BIEN	USABLE	REPARAR	CAMBIAR	ND	Observaciones	Coste estimado		
								Repuestos	Mano de obra	Total
Did you take a picture of?							✓ Discharge auger showing diameter			

BMLSS- BROKEN-MISSING-LEAKING-SAFETY-SERVICE-

	NUEVO	BIEN	USABLE	REPARAR	CAMBIAR	ND	Observaciones	Coste estimado		
								Repuestos	Mano de obra	Total
Each section must be completed or it will be returned-							✓ Each section must be completed or it will be returned-			
My expected broken items cost and description							✓ No Broken Items			
My missing items replacement cost and description							✓ No missing items			
My expected leaking items cost and description							✓ No leaking items			
My expected safety items cost and description							✓ No safety items to fix			
My expected Service costs and description (Example:oil-fluids-filters-wash)							✓ Cost and description of oil-fluids-filters and wash and to put on front line-enter in notes 2500 wash it and put on lot.			

PRICING

	NUEVO	BIEN	USABLE	REPARAR	CAMBIAR	ND	Observaciones	Coste estimado		
								Repuestos	Mano de obra	Total
Total BMLSS cost (must be broken down in section above)							✓ Total BMLSS cost (must be broken down in section above) 2500			
My expected sale price							105000			