



INSPECCIÀN EVALUACIÀN — ADVANCED — USED ASSESSMENT

2022 John Deere 5100M

Inventario: 679244

Número de serie: 1PY5100MCNB002481

Garantía desconocida

LOCALIDAD ALMACENAMIENTO

Green Diamond Equipment Ltd. / 731644

Napan, NB, E1N 5G2

Contacto:

FOTOS (0 Total)

RESUMEN

Estado general:

Comentarios

generales:

Horas:

	EXCELENTE	BIEN	MEDIANO	RAZONABLE	MAL	N/A	Observaciones	Coste estimado		
								Repuestos	Mano de obra	Total
unit information				X				0	0	0

UNIT INFORMATION

	NUEVO	BIEN	USABLE	REPARAR	CAMBIAR	ND	Observaciones	Coste estimado		
								Repuestos	Mano de obra	Total
model and serial number							2022 John Deere 5100M 1PY5100MCNB002481			
unit hours							287			
estimated hours if not being traded straight away										
[tire_cond]										
attachments included in possible trade. please supply serial numbers, model and description										
ENGINE AREA oil and coolant level, does unit require a service ? fuel sediment bowl check for water. fuel lines/ coolant/A.C lines- leaks ?. cooling pack condition, alternator belts and pulley condition, hydraulic lines.		X								
POWERTRAIN axle seals front and back, front MFWD hub seals, front axle pivot, wheel rims, steering cylinders. drive unit, run through the gears, check operation of reverser, gearshift and ranges.		X								
OPERATOR STATION. seat operation and condition, windows and doors, heater and A/C operation. lights, gauges and monitor. check for active error codes. GPS. receiver and display model's and serial numbers (if not integral with tractor) ATU model if fitted		X								
PANELS AND FRAME/PAINT. are all and any safety shields in place, SMV sign present, are any panels/hood/fenders damaged. Paint condition. are there frame/cassette weights ?				X			Missing RH step, missing RH & LH side panel of hood, missing draw bar & draw bar support. Missing Top link.			
PICTURE CHECK LIST unit serial number, all four corners, rear , close up of the rear showing scv's and PTO. operator station X Si O No right hand side controls , unit current hours, seat(s), attachments/loader model and serial numbers X Si O No										
hydraulics hydraulic scv's, loader couplers and quick attach, leaks, damage, function. hydraulic cylinders, hoses rubber and steel. leaks or damage. cylinder pins and retainers		X					No visible leaks			
has owner/operator noticed any leaks, damage or impaired functions ?							no			
has there been any modifications to the emissions system or engine management system ??							no			